


Hookup diagram for LC Meter kit



Capacitor/Inductor connections, use alligator clips or other test clips / test fixture. Connect one terminal of the part under test to either Cx or Lx and the other terminal to Ground.

Jackson Harbor Press
<http://jacksonharbor.home.att.net/>
jacksonharbor@att.net